

COL T S PLAHA
FIV ,FIE .(INDIA)
BE (CIVIL) ME (STRUCTURES)
PGD IN B& IM and Eco & Env
CERTIFICATE IN SOLAR ENERGY
CHARTERED ENGINEER(I)
Addl: Chief Engr. (retd)
Registered & Govt.Approved Valuer
Regd No .CC/CHD/TECH/II/Valuer/170
U/S-34 Ab of Wealth Tax Act –Teg
PROP TARA CONSTRUCTION CO

KOTHI NO :30
PHASE-9,MOHALI (PB)-160062
PHONE :0172-5058027
MOBILE: 9814166507
9814388507,9417266507,
9056566507.
E-mail : colplaha7@gmail.com
colplaha@hotmail.com
Office :2553, Sector 47- c,
Chandigarh -160047

To Whom It May Concern

Having been engaged for issuing the certificate for the Safety & Security of School buildings, I have visited the school premises of Primary School and Hr Sec School of Sec 47, Chandigarh alongwith the Ptnicipal on 17 Apr, 2021. I am of the opinion that the Double storeyed buildings of Primary School and Triple Storeyed building of Hr Sec School are **structurally sound and are safe** . The TRS Huts in Hr Sec School In L Block are quite old have outlived their shelf life **however these can be used for running the classes** . **These should be maintained properly & be got repaired at the earliest under the Head“Special Repairs”**.

2. The TRS Hut near the Main Entrance Gate have developed diagonal Cracks as shown in the photographs. These Diagonal cracks have developed because of the settlement of foundation in the rear wall of the building . The settlement has occured probably due to water logging in the area as there is no proper drainage and water has seeped into the foundation. The immediate remedial measure is to construct Plinth Protection walls and Buttress walls along the rear wall opposite to the partition walls of the rooms to protect the building from further deterioration . The class rooms numbered 19 to 24 in the building has been locked by the Principal for safety of the children till suchtime the remedial measures are not completed.


3. Secondly the School premises of Primary & Higher Secondary School s have been provided with boundary wall with gate all around and are well secured, The boundary wall of the school are recommended to be provided with Barbed wire fencing with concertina coils on top . The photographs of the school buildings are attached.

4. The full grown Tall Eucplous Trees near the Main Building & TRS Huts are recommended to be cut as it may cause damage to the buildings during storms

5. The case may please be initiated through proper channel and recommendation of local counsellor for allotment of funds for carrying out special repairs through Chief Engr UT Admn.

Place : Chandigarh/ Mohali

Dated 17 Apr, 2021


Col TS Plaha (Retd)
Govt Approved Valuer &
Structural Engineer

Col T S PLAHA
FIV,FIE(I)Ch(I),MICA
STRUCTURAL ENGR,
& CHARTERED ENGR,